

HISTORIC AMERICAN BUILDINGS SURVEY
INDEX TO PHOTOGRAPHS

HABS
MD,
2-CUMB.V,
1-

Cedar Park
Lothian Vicinity
Anne Arundel County
Maryland

HABS No. MD-847

Randolph Langenbach, Photographer 1973

- MD-847-~~1~~⁹ PERSPECTIVE VIEW OF WEST (REAR) ELEVATION
- MD-847-~~2~~¹⁰ PERSPECTIVE VIEW OF NORTH GABLE, SHOWING ENTRANCE PORCH, CHIMNEY
STACK AND "SALT BOX" ROOF
- MD-847-~~3~~¹¹ EAST (FRONT) ELEVATION, VIEW SHOWING ENTRANCE PORCH ADDITION
- MD-847-~~4~~¹² EAST (FRONT) ELEVATION, DETAIL OF SOUTHEAST CORNER
- MD-847-~~5~~¹³ GROUND FLOOR, SOUTH ROOM, SOUTH WALL, DETAIL SHOWING FIREPLACE
AND WALL PANELING
- MD-847-~~6~~¹⁴ ORIGINAL CELLAR, EXCAVATED SOUTHWEST CORNER
- MD-847-~~7~~¹⁵ INTERRUPTED SILL, SEATED AND MORTICED INTO HOLE-SET POST (NOTE
LOWER END CUT OFF AND SHOVED UP WITH BRICK UNDERPINNING)
- MD-847-~~8~~¹⁶ SOUTHWEST CORNER OF EAVES, SHOWING CONSTRUCTION TECHNIQUES OF
FIRST BUILDING PHASE
- MD-847-~~9~~¹⁷ SOUTHWEST CORNER OF EAVES, SHOWING CONSTRUCTION TECHNIQUES OF
FIRST BUILDING PHASE
- MD-847-~~10~~¹⁸ SOUTHWEST CORNER OF EAVES, SHOWING CONSTRUCTION TECHNIQUES OF
FIRST BUILDING PHASE
- MD-847-~~11~~¹⁹ ROOF FRAME, EAST SLOPE, DETAIL SHOWING VALLEY RAFTERS FOR PORCH
TOWER
- MD-847-~~12~~²⁰ ROOF FRAME, WEST SLOPE
- MD-847-~~13~~²¹ ROOF FRAME, EAST SLOPE, DETAIL SHOWING VALLEY RAFTERS FOR ORIGINAL
DORMER
- MD-847-~~14~~²² ROOF FRAME, EAST SLOPE, WOODEN GUTTER FROM VALLEY RAFTER TO PORCH
- MD-847-~~15~~²³ ROOF FRAME, EAST SLOPE, WOODEN GUTTER ALONG NORTH VALLEY RAFTER TO
PORCH TOWER